

TOP SECRET

HANDLE VIA [REDACTED]

Approved For Release 2003/01/24 : CIA-RDP63-00313A000500040012-0

CONTROL SYSTEM ONLY

23 January 1963

25X1A

MEMORANDUM FOR: The Special Group

SUBJECT: Permission for a TACKLE Mission  
to the Szechwan Basin

1. Two TACKLE missions directed at the Szechwan  
Basin (24 December and 20 January), [REDACTED]

25X2

25X2 [ ]

[REDACTED] have failed because of camera mal-  
function. Permission is requested to mount another mission  
at this target as soon as feasible.

2. The Hy Con camera experts through extensive  
tests have determined that the cause of malfunction lies in the  
vacuum solenoid. This device which controls the movement of  
the film has been rebuilt to replace a cadmium lining with nickel.  
This replacement, thoroughly tested, will be installed before  
any further TACKLE missions are made. This should be accom-  
plished by 23 January. The answer to why this fault has not  
shown itself in previous years is obscure but it is believed  
associated with the age and protracted use of the equipment.

25X1A

[REDACTED]  
HERBERT SCOVILLE, JR.  
Deputy Director  
(Research)

25X1A

TOP SECRET